


# REPLACEMENT – CUTTING & WELDING TIPS


## SUITABLE FOR PUROX LINDE / L-TEC

SKETCH & DESCRIPTION FUEL TIP STYLE SIZES PART NUMBER

	4203 GENERAL	Propane - Oxygen	4203	4..... 16K15
				5..... 16K16
				7..... 16K17
				9..... 16K18
				11..... 16K19


ALL SIZES  
\$25.50 EA

Medium preheat for general cutting with propane. One-piece. Also available in two-piece for all sizes.

	4205 CAST IRON	Acetylene - Oxygen	4205	4..... 16K26
				5..... 16K27
				7..... 16K28
				9..... 16K29
				11..... 16K30


**OBSOLETE**

Heavy preheat for cutting cast iron, demolition work, etc.

	4206 DRAG	Acetylene - Oxygen	4206	3..... 16K31
				5..... 16K33


ALL SIZES  
\$47.95 EA

Light preheat, drag type for cutting and trimming light plate. One preheat hole.

	4207 GOUGE	Acetylene - Oxygen	4207	13..... 16K67
				19..... 16K35


ALL SIZES  
\$47.95 EA

Medium preheat for grooving, gouging and removing defective welds.

	4208 GENERAL	Propane - Oxygen Natural Gas-Oxygen	4208	4..... 16K36	
					5..... 16K37
					7..... 16K38
					9..... 16K39
					11..... 16K40


**OBSOLETE**

Medium preheat for general cutting with propane or natural gas. One piece.

	4209 30° BENT RIVET	Acetylene - Oxygen	4209	5..... 16K47


\$65.00 EA

Medium preheat-2 preheat holes. For cutting close to bulkheads, rivet heads, etc..

	4211 SCRAP CUTTING	Propane - Oxygen -or- Natural Gas-Oxygen	4211	4..... 16K56	
					5..... 16K57
					7..... 16K51
					9..... 16K52
					11..... 16K58


**OBSOLETE**

Heavy preheat for scrap cutting operations. One piece.

	4212 SCRAP CUTTING	Acetylene - Oxygen	4212	3..... 16K59
				4..... 16K60
				5..... 16K61
				7..... 16K62
				9..... 16K63
				11..... 16K64
				13..... 16K65


**OBSOLETE**

Heavy preheat. For cutting scrap, demolition work, etc.

	4213 - 4214 GENERAL	Fuel Gas - Oxygen	4213 - 4214	3..... 16L02
				4..... 16L03
				6..... 16L04
				8..... 16L05
				10..... 16L06
				12..... 16L07

ALL SIZES  
\$27.14 EA

Medium preheat. For general cutting with propane or natural gas. Two piece.

	4217 INTERNALS	Fuel Gas - Oxygen	4217	3..... 16K68
				4..... 16K69
				6..... 16K70
				8..... 16K71
				10..... 16K72
				12..... 16K73


ALL SIZES  
\$25.00 EA

General duty hand cutting. Uses 16K74 & 16K75 external sleeves.

	4214 - 4218 EXTERNAL SLEEVE	4214 / 4218	3 & 4..... 16K74
			6 - 12..... 16K75

ALL SIZES  
\$17.50

SKETCH & DESCRIPTION FUEL TIP STYLE SIZES PART NUMBER

	W-300 GENERAL WELDING	W-300	SIZES 2 - 6	2 ..... 06L24
			\$38.00 EA	4 ..... 06L25
				6 ..... 06L26

SIZES 9 - 15  
\$45.00 EA

SIZES 55 - 100  
\$130.00 EA

Complete welding tip and mixer.



Nut for W-300

NUT and SNAP RING..... 12K10

\$15.95 EA

	W-200 GENERAL WELDING	W-200	1 ..... 06L01
			2 ..... 06L02
			4 ..... 06L03
			6 ..... 06L04
			9 ..... 06L05

ALL SIZES  
\$35.00 EA

15 ..... 06L06

30 ..... 06L07

Complete welding tip and mixer.

Nut for W-200




NUT and SNAP RING..... 12K15

\$15.95 EA


## SUITABLE FOR PRESTOWELD

SKETCH & DESCRIPTION FUEL TIP STYLE SIZES PART NUMBER

	C-111-4 GENERAL	Acetylene - Oxygen	C-111-4	0 ..... 08Z63
				1 ..... 08Z53
				2 ..... 08Z54
				3 ..... 08Z55
				4 ..... 08Z56


ALL SIZES  
**OBSOLETE**

Light preheat. For general cutting operations. Use Purox 4201 Series

	C-111-6 GENERAL	Acetylene - Oxygen	C-111-6	1 ..... 65Z17
				2 ..... 65Z18
				3 ..... 65Z19
				4 ..... 65Z20

ALL SIZES  
**OBSOLETE**

Medium preheat. For general cutting operations. Use Purox 4202 Series

	C-111-P GENERAL	Propane - Oxygen	C-111-P	1 ..... 08Z96
				2 ..... 08Z97
				3 ..... 08Z98
				4 ..... 08Z99

ALL SIZES  
**OBSOLETE**

Medium preheat. For general cutting with propane or natural gas. Use Purox 4203 Series

	W-121 & W-122 GENERAL WELDING	W-121 & W-122	2 ..... 20K83
			4 ..... 20K84
			6 ..... 20K85
			9 ..... 20K86
			15 ..... 20K88
			30 ..... 20K90
			55 ..... 20K92
			70 ..... 20K93
			100 ..... 20K95

**OBSOLETE**

General welding. Bent elbow copper tip only.