



FOR PRICE LISTING
GO TO PAGE 317


PLASMA CUTTING

Replacement Parts

Suitable For

MILLER®


Torch Model	Power Supply Model
ICE-50C / 50CM	SPECTRUM® 650, 701, 2050



Suitable For

MILLER®

Torch Model	Power Supply Model
ICE-55C / 55CM	SPECTRUM® 2255




ITEMS NOT SHOWN

- T-2515 Hand Torch
 - T-2516 Machine Torch
- Note: To use ICE-55C Nozzles on the ICE-50C torch, switch the Swirl Ring (Part # T-1742)

REQUIREMENTS:




Gas: Air, Nitrogen
Pressure: 70 psi
Flow: 5,3 scfm



Suitable For

MILLER®

Torch Model	Power Supply Model
ICE-70/70M, ICE100,100M	SPECTRUM® 1000, 1250




ITEMS NOT SHOWN

- T-2857 Leads Assy, 30'
- T-2856 Torch w/Leads Assy, 30'
- T-1420 Torch, ICE-70, ICE-100

Suitable For

MILLER®

Torch Model	Power Supply Model
ICE-80C, 80CM	




ITEMS NOT SHOWN

- T-2501 Tip, Gouging
- T-2502 Shield, Gouging
- T-2503 Hand Torch
- T-2504 Machine Torch

REQUIREMENTS:

Gas: Air, Nitrogen
Pressure: 65 psi
Flow: 6,7 scfm



Suitable For

MULTIQUIP®


Torch Model	Power Supply Model
PCX 50SS	



Suitable For

NUTECSYS®


Torch Model	Power Supply Model
NPT-3, 3R & 3S	



Suitable For

NUTECSYS®

Torch Model	Power Supply Model
NPT-12	



**For NUTECSYS Torch Models:
NPT- 4, 5, 6, & 7
use Binzel PSB 60/80/121
Parts**

"()" = Alternate Number