



**FOR PRICE LISTING
GO TO PAGE 317**

PLASMA CUTTING


Replacement Parts

Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model Power Supply Model

PT-25 ESP-100I, PCM-150 (W/ADAPTER)



ACCESSORIES Suitable For

ESAB® (L-TEC® / Linde®)


Torch Model Power Supply Model

PT-25 ESP-100I, PCM-150 (W/ADAPTER)



Leads Assembly


T-578 Leads Assy 25' T-579 Leads Assy 50'



ITEM NOT SHOWN

- T-2262 Flex Support
- T-2263 Sensor Tube, 25'
- T-2264 Sensor Tube, 50'

REQUIREMENTS:
Plasma Gas: Air, Nitrogen
Shield Gas: Air, N₂, CO₂
Pressure: 70 psi
Flow: Plasma 200 cfh
Shield 360 cfh




Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model Power Supply Model

PT-26 ESP-200 & DEUCE PACK 150




Suitable For


ESAB® (L-TEC® / Linde®)

Torch Model Power Supply Model

PT-31, PT-31XL & XT PCM-500I/875/1125/SMI



FOR PT-31XT ONLY



T-357 O-Ring



ITEMS NOT SHOWN

- T-1893 Seat, Brass
- T-1883 Tip, 50 amp

XL, XT and Standard Parts Should Not Be Mixed When Cutting

*Use T-1172 Plunger only with T-1173 Electrode

Requirements:
Gas: Air
Pressure: 75 psi
Flow: 4.5 scfh
Max. Thickness: